

| | A | B | C | D | E | F | G |
|-----|----------------|----------|---------|------------------------|-----------|---|--|
| 102 | Minor Incident | 01/10/15 | 12.30 | Rotary site | discharge | Lack of awareness and concentration by 360 excavator operator | Whilst the 360 Excavator was cleaning up around the oscillator, he caught the hydraulic hose with the bucket causing damage to the hose and the fitting and approx. 1 pint of hydraulic oil sprayed onto the floor. |
| 103 | Minor Incident | 02/10/15 | 18:00 | Rotary site | discharge | Sheathing from the hoses not replaced | Whilst installing a 1500dia casing with the Casagrande B360, the hydraulic hoses which were hanging down side of the rig and caught the twist bar causing the hydraulic hoses to stretch spraying approx. 500ml of hydraulic oil on to the casing and a little on the ground. |
| 104 | Minor Incident | 21/10/15 | 1400.00 | CFA/DFA site | Spill | Loose Hose | Minor incident cleaned up immediately due to loose hose on the rig |
| 105 | Minor Incident | 19/11/15 | 14:15 | Driven site | Spill | Wear and tear | The Junttan Piling rig (J29) was pitching a pile; however as they closed the gates they noticed that hydraulic oil (approx. 2L) was spilling out of the pressure hose. Despite majority being caught in the bagging, a little has spilled onto the platform. |
| 106 | Near miss | 20/11/15 | 13:45 | Rotary site | Spill | Lapse by wagon driver, where the load was strapped | Haulier (William Walker Transport) arrived on site to deliver the powerpack and oscillator from Bottesford Yard strapped on the back of the trailer; however during transit the strap holding the powerpack was strapped over the fuel tank causing it to split the tank. This caused diesel to spill from Bottesford Yard to Aberdeen - note: the driver heard a bang whilst driving, pulled over and noticed that the oscillator had moved. The driver took the opportunity to re-strap the oscillator and the powerpack. It has also been noted that the hydraulic pipe on the oscillator has snapped, causing hydraulic oil to leak along the route as well. |
| 107 | Near miss | 27/11/15 | 12:15 | Rotary site | Spill | Hydraulic hoses leak | Hydraulic loop hoses x 3 caught between track and motorhead carriage |
| 108 | Near miss | 30/11/15 | 16:12 | Rotary site | other | Extractor Fans not in place | Extractor Fans on site - but not in place and carbon monoxide /gas reader needs purchasing |
| 109 | Near miss | 30/11/15 | 16:12 | Rotary site | Spill | Hose failure | Major Hydraulic hose failure in engine area of piling rig |
| 110 | Near miss | 30/11/15 | 15:00 | Rotary site | Spill | wear and tear, general maintenance | Concrete pump suffered small leak. Oil pads and granules used to soak up oil. Collected by licenced waste carrier |
| 111 | Minor Incident | 02/12/15 | 12.30 | Driven site | Spill | Tracks became caught on steel plate | There is a steel plate on the floor covering the manhole; however as the rig tracked over the steel plate to head towards a diesel bowser to fuel the rig. The steel plate became caught between the rig tracks and flicked up under the machine and caught a hydraulic pipe causing it to spill hydraulic oil (25L) onto the platform but missed the manhole. |
| 112 | Minor Incident | 05/12/15 | 09:00 | Plant Yard or Workshop | Spill | Wear and tear | A small bore pipe (1/4 dia) low pressure line to auxiliary spool control on the hired 8T digger has burst causing less than 1L of oil to spill on the floor. |
| 113 | Minor Incident | 08/12/15 | 21:30 | Rotary site | Spill | Wear and tear | Whilst they were cleaning the street following a muckaway wagon; the hydraulic hose on the roadsweeper burst causing hydraulic oil to spill (approx. 5 to 10L) and spread over the road. |
| 114 | Near miss | 09/12/15 | 12:25 | Rotary site | Spill | Split hose | Split hose on MP5004 |
| 115 | Minor Incident | 15/12/15 | 11:30 | Driven site | Spill | Loose connection | A hydraulic pipe became loose at the connection however they were unable to tighten it back on causing hydraulic oil (a minimal amount) to spill onto the platform. |
| 116 | Minor Incident | 15/12/15 | 17:15 | Rotary site | Spill | Wear and tear | Whilst screwing the casings down, the hydraulic hose on the hired oscillator burst causing hydraulic oil to spill approx. 5L on the platform. Site are currently 20m away from the nearest water course however there was little chance of contamination. |
| 117 | Minor Incident | 16/12/15 | 16:30 | CFA/DFA site | Spill | Wear and tear | Whilst extracting / concreting the last pile of the day (approx. 6.5m from completion) the hydraulic hose burst spilling hydraulic oil onto the platform (approx. 40 - 50L). |
| 118 | Minor Incident | 29/12/15 | 14:20 | CFA/DFA site | Spill | Wear and tear | Hutchinson's Lowloader had unloaded the piling rig at the site entrance on the North side of the station. The low loader then drove away from the site North side entrance, drove some 70mtrs on the public highway when a hydraulic hose burst spilling approx. 5L of hydraulic oil onto the road at the junction of Rushden Road and the main compound site entrance. |