

ref	Accident Severity / Category	Date of accident (dd/mm/yy)	Age	Nº years experience	Shift start time (24 Hr)	Time of accident (24 Hr)	Place of Accident	Foundation Site Activity	Function / Trade (at time of accident)	Activity of IP (at time of accident)	Body part injured	Type of Injury	Basic cause	Outline / Description
2017/108	1 -7 day LTA	04/07/17	53	>3 years	7.30am	09.20am	Site	Drilling/Multiple site	Foreman/Ganger/Charg ehand	Other	Eye	Laceration	Struck by	The IP was clearing spoil from the casing, whilst doing this a piece of spoil projected from the drill head hitting the back of the IP's helmet. This caused the IP's head downwards striking the protruding drill steel.
2017/109	1 -7 day LTA	14/08/17	31	1-3 years	7.30am	09.30am	Site	Drilling/Multiple site	General Piling Operative	Manual Handling - other manual handling	Hand / Wrist	Laceration	Manual handling	The IP trapped his finger whilst unloading a rig shock absorber (54kg) from trailer bed.
2017/110	1 -7 day LTA	17/07/17	38	< 1 year	6:00am	13:30pm	Factory	Factory Premises	Workshop /Factory Operative	Walking	Ankle / Foot	SPRAIN/STRAIN	Trip / Slip	IP was setting up the concrete moulds in the factory when he lost his footing and slipped, spraining his ankle.
2017/111	1 -7 day LTA	27/07/17	50	< 1 year	6:00am	12:20am	Factory	Factory Premises	Workshop /Factory Operative	Manual Handling - other manual handling	Finger / Thumb	Laceration	Struck against	IP was using a pry bar when this slipped and the momentum caused his hand to hit the mould, causing his injury.
2017/112	+7 day LTA	25/07/17	55	1-3 years	6:00am	10:15am	Site	Drilling/Multiple site	General Piling Operative	Manual Handling - other manual handling	Back	SPRAIN/STRAIN	Manual handling	IP was testing recently installed ground anchors- when he overreached and attempted to pick up a 32kg testing plate. He pulled his back in the process.
2017/113	+7 day LTA	03/08/17	27	< 1 year	22:00pm	00:30am	Factory	Factory Premises	Workshop /Factory Operative	Maintenance	Back	SPRAIN/STRAIN	Fall below 2m	IP was changing the robot welder face plate former when he lost his footing and fell into the pit below.
2017/114	+7 day LTA	11/08/17	41	< 1 year	14:00pm	19:00pm	Factory	Factory Premises	Workshop /Factory Operative	Maintenance	Arm	SPRAIN/STRAIN	Struck against	IP was tightening a bolt when the bolt head sheared and the momentum caused him to injure his right arm.
2017/115	1 -7 day LTA	29/08/17	48	>3 years	6:00am	09:25am	Factory	Factory Premises	Workshop /Factory Operative	Manual Handling - other manual handling	Finger / Thumb	Laceration	Struck against	IP was removing the saw clamp spacing plate using a length of 3xx3 timber. This slipped causing IP to strike his hand and injure his middle finger.
2017/116	1 -7 day LTA	24/08/17	28	1-3 years	7.30am	15.10pm	Site	CFA/DFA site	Mixer / Pump man	Mechanical handling	Torso	Other	Struck by	Was working as a Pump Operator but went to help the banksman. The auger on an SFS0 had gone to far into the gate section and got caught in the gate inserts this caused the gates to be forced open just as the IP looked over the barrier and the gate opening bar had been left in place which struck IP in the ribs throwing him to the floor.
2017/117	+7 day LTA	29/08/17	44	>3 years	07.30 a.m	11.30 a.m.	Site	Drilling/Multiple site	Foreman/Ganger/Charg ehand	Manual Handling - handling construction materials	Finger / Thumb	Laceration	Trapped	Equipment was being moved from the road to the crane hoist area with a manually operated pallet truck. The IP was walking by and was asked to assist by the pallet truck operator. The operator pushed the sillage & the IP pulled the sillage and trapped his hand against an RSJ that was concealed by polythene.
2017/118	+7 day LTA	25/09/17	49	>3 years	7.30	10:50	Site	Driven site	General Piling Operative	Other	Finger / Thumb	Fracture	Trapped	Prior to pitching a precast concrete pile into the pile helmet, the piles were lifted and turned so the pile joints were in the correct orientation. The pile made contact with the gates on the mast and crushed the rig attendant's right index finger resulting in surgery.
2017/119	1 -7 day LTA	14/07/17		>3 years	7.30	14.05	Site	Rotary site	General Piling Operative	Walking	Ankle / Foot	Other	Trip / Slip	The injured party was walking along the side of the wagon on the piling platform. The injured party was looking up at the load on the wagon, which caused him to lose focus on where he was walking. The injured party then stood in a rut, causing him to stumble and twist his ankle.
2017/120	1 -7 day LTA	19/07/17		>3 years	7.30	18:30	Site	Rotary site	General Piling Operative	Manual Handling - handling construction materials	Finger / Thumb	Laceration	Trapped	An Operatives cut his finger on both sides on his left index finger whilst concreting. The injured party was attaching a hopper to the tremmie trap when the hook, which is used to attach to the hopper, had become caught. The injured party attempted to release the hook, which released as he tried to grab it and cutting his finger in two places.
2017/121	1 -7 day LTA	14-Sep	29	>3 years	7.30	13:00	Site	Rotary site	General Piling Operative	Other	Eye	Other	Other	While installing a 10 metre casing into pier 12 without a pre-bore (pre bore could not be achieved due to ground conditions), the casing was approximately 4m into the ground when the injured party felt something in his eye. All exclusion zones were in place during the operation and the injured party was outside of the exclusion zone. The injured party was wearing all necessary PPE, including light eye protection. Possible weather conditions picking up dust from site; airborne dust particles entering eye.
2017/122	Specified Injury	23/08/17	48	>3 years	7.00	12:54	Site	Rotary site	General Piling Operative	Other	Leg	Fracture	Struck by	The general piling activities for the day was to complete 5 No piles, unload segmental casing from a delivery vehicle and load the lorry with 4 No. 600d casings which were being stored on the ground near the high level platform ramp, waiting to be de-mobilised. To facilitate access for another contractor's concrete truck, 1 No. casing was moved and placed on top of the other 3 No. Chocks were in place either side of the casing stack to secure them. The 11.2t chains, stored near the end of the casings, were needed to unload the delivery vehicle. The IP fitted the chains and put them onto the crane hook block and signalled the crane driver to hoist. The IP then sat on the casings in the gap between the casing stack and a storage sillage. When the crane started to hoist upwards one of the shorteners of the 4-leg 11.2t chains attached itself to the casing he was leaning on, causing it to lift above the chock. The lower casing then moved laterally, caused by the weight of the stacked casing, trapping the IP's leg against the sillage. An excavator was used to push the sillage to free the IP. After assessment by the site first aider the IP was taken to the nearest hospital. The IP has suffered a fracture to his right fibula.
2017/123	+7 day LTA	08/08/17	52	>3 years	07:30am	17:00	Site	Grouting site	General Piling Operative	Manual Handling - other manual handling	Multiple / whole body	Other	Trip / Slip	The IP stepped backwards over a groud hose that was being moved. In doing so he tripped on rough ground resulting in injuries
2017/124	1 -7 day LTA	13/07/17	32		7.30	14:50		Drilling/Multiple site	General Piling Operative	Other	Finger / Thumb	Laceration	Trapped	During an operation to re-connect the mini rig drilling table to the auger string, the machine operator moved the drilling head and the IP trapped his finger causing lacerations to his right hand ring finger.

ref	Accident Severity / Category	Date of accident (dd/mm/yy)	Age	N° years experience	Shift start time (24 Hr)	Time of accident (24 Hr)	Place of Accident	Foundation Site Activity	Function / Trade (at time of accident)	Activity of IP (at time of accident)	Body part Injured	Type of Injury	Basic cause	Outline / Description
2017/125	1 -7 day LTA	23/08/17	27	< 1 year	8AM	9:30AM	Site	CFA/DFA site	General Piling Operative	Walking	Shoulder	Other	Struck by	The IP was outside of the secure safety zone, a stone fell from height deflected off the concrete hose and landed onto the IP's shoulder. The IP suffered a small amount of contusion to the shoulder.
2017/126	1 -7 day LTA	23/09/17	47	>3 years	8AM	10:30AM	yard	Plant Yard or Workshop	Filter / Elec / Welder	Mobilisation / demobilisation	Finger / Thumb	Other	Trapped	IP was holding the service line as the rig was being de-rigged, he didn't notice the baby weight stuck behind the auger cleaner, the weight became free and slid 800mm down the service line trapping the IP's finger between the weight and the crimp of the rope. The IP's index finger sustained contusion.
2017/127	+7 day LTA	23/08/17	56	>3 years	07:30am	15:45:00	Other	Not identified	Foreman/Ganger/Charg ehand	Mobilisation / demobilisation	Ankle / Foot	Other	Not identified	The "IP" was involved in the loading of plant and equipment from a quayside onto a barge during the mobilisation of a marine project. The barge was secured to the quayside by 2 X ties at opposite ends of the barge and a spud leg that was lowered into the sea bed. A tug boat was in situ to position and tow the barge to its destination. Due to the late arrival of the tug, the tide began to go out, and as the ties and spud leg were removed / raised the "IP" decided to jump off the barge (gap approximately 4ft / 1.2m) onto the quayside instead of waiting until the barge could be repositioned closer to land by the tug. As the "IP" landed he bruised the bottom of his foot resulting in a >7 day LTA RIDDOR reportable injury.
2017/128	Specified Injury	15/09/17	51	>3 years	07:30am	17:04:00	Site	Rotary site	Filter / Elec / Welder	Mobilisation / demobilisation	Finger / Thumb	Multiple	Trapped	As the site filter was using a slide hammer to remove the final securing pin on a BG46 which during the demobilisation (the winch was slung and connected to the attendant crawler crane), it was reported the winch moved slightly trapping the "IP's" right hand wedding ring finger. This resulted in an amputation and severe laceration below the top knuckle. Investigations are ongoing.
2017/129	Specified Injury	04/07/17	27	< 1 year	8.00	9	Site	Rotary site	General Piling Operative	Walking	Ankle / Foot	Other	Other	Operative was loading metal sheeting into the lift and caught his foot on a piece of the goods lift flooring that had come loose.
2017/130	Specified Injury	05/07/17	45	>3 years	8.00	10	site	CFA/DFA site	Foreman/Ganger/Charg ehand	Manual Handling - handling construction materials	Hand / Wrist	Laceration	Struck by	Taking pins out of SR75 auger section IP was holding the nail pin and as the operator swung the club hammer, missed pin and hit finger.
2017/131	Specified Injury	08/09/17	30	1-3 years	08:00:00	1400	site	Rotary site	General Piling Operative	Walking	Ankle / Foot	Other	Other	IP walking through site kicked aside a hard hat not realising it was filled with hardened concrete. IP reported feeling soreness to the outside edge of his right foot and suffered minor bruising to right big toe.
2017/132	Specified Injury	18-Sep	40	< 1 year	08:00:00	09:30	Site	Rotary site	General Piling Operative	Manual Handling - handling construction materials	Hand / Wrist	Laceration	Struck by	Whilst IP was trimming down the piles he tent his left hand against the pile rebar causing him to cut his left thumb
2017/133	Specified Injury	28-Sep	29	1-3 years	08:00:00	18:00	Site	CFA/DFA site	General Piling Operative	Maintenance	Head	Laceration	Struck by	IP attempted to start up jet wash to clean out concrete pump. As he switched on ignition with the trigger of the gun, held back by a bottle to help with aid of start up process the gun with pressurised water flowed out the nozzle and struck IP's face.

Near miss	11/07/17	11:30	Rotary site	Spill	Hydraulic seal failure on MP6001	Spillage was cleaned up with granules
Near miss	06/07/17	8:00	Factory/Premises	Other	procedure not followed	An IBC was noted stored in the yard on the floor - poor pollution prevent control measures. No spill or leak occurred
Minor Incident	03/07/17	10:00	Rotary site	Spill	Wear and Tear	There was a hydraulic leak on the accumulator on the rotary table. Approximately half a litre of hydraulic oil was spilled onto the platform.
Minor Incident	18/07/17	10:10	Rotary site	discharge	Pressure of the bentonite	Whilst desanding pile 19 the rubber seal blew out the valve, causing a spray of bentonite to be released on the piling platform. Approximately 25l of bentonite was spill.
Minor Incident	18/07/17	14:30	Driven site	Spill	Wear and Tear	A few spots of oil were noticed on the ground next the pile position which was being driven. Approximately 1/4 litre of hydraulic oil was spilled onto the platform.
Minor Incident	20/07/17	08:00	Driven site	Spill	Slight leak on the valve block	During the rig inspection it was noticed that on the hammer rope winch, the valve block was soaked in hydraulic oil. Approximately 100ml of oil has spill onto the platform.
Minor Incident	28/07/17	17:00	Vibro / Ground stab'n site	discharge	Wear and Tear	During the pre-boring operation of the columns with the hired machine, a hydraulic hose burst on the mast above the motor table.
Minor Incident	01/08/17	14:30	CFAD/FA site	Spill	Small piece of metal was lodged within the quick release hose allowing for oil to leak after disconnection	While the BBGE Fitter was de-rigging the B175 (1088), some hydraulic oil was spilled onto the platform. The quick release hose was connected to the foot section and had leaked approx. 100ml of oil.
Minor Incident	07/08/17	12:55	Rotary site	discharge	Faulty check valve	While dismantling the oscillator on site, they removed the hoses when they noticed that one of the fittings on the power pack was leaking. There was a drip tray in place, but when they took the power pack it leaked approx. 2L of hydraulic oil onto the platform.
Minor Incident	15/08/17	17:00	Driven site	Spill	Wear and Tear	It was noticed there were a couple of drops of hydraulic oil on the track and on the platform. There was only a minimal spillage caused by a crack in a hose behind the cab.
Minor Incident	22/08/17	14:20	CFAD/FA site	discharge	Wear and Tear	It was noticed there was a hydraulic oil leak coming from a hose on the mini piling rig (approx. a cupful).
Minor Incident	30/08/17	09:30	Rotary site	Spill	Bentonite line valve not tightened effectively	A valve on a bentonite line had not been closed properly, which caused approximately half a cube of bentonite to spill into where the last pile was being constructed.
Minor Incident	30/08/17	16:25	Rotary site	Spill	Blockage in pump	Bentonite spillage when breaking tremmies whilst desanding. Approximately 50l of bentonite was spilled into the BBGE work area.
Minor Incident	19/09/17	08:00	Driven site	Spill	Small oil leak	It was discovered that there was approximately half a litre of hydraulic oil spill onto the platform. It was found that there was a very small oil leak on the piling rig as there was a hydraulic fitting which required tightening.
Minor Incident	26/07/17	10:00	Drilling/Multiple site	Spill	Rig malfunction	During drilling operations with a twin 308 piling rig the engine oil tank cap became loose due to vibration of the power pack spilling approx. 1 gallon of oil onto hard standing ground. A spill kit was used to prevent further movement of the oil and to contain the spillage. A Filter was called to site to refill the engine and to fix the tank cap. Supervisor is aware. No injuries.
Near miss	09/08/17	00:00	CFAD/FA site	other	Transport/equipment interaction	A vehicle tracked over bentonite pipes which caused flat spots however no spill took place as it was identified and monitored until new pipes could be fitted the next day.
Minor Incident	21/07/17	9:30	Rotary site	Spill	Hose burst	One of the main hydraulic hoses on the BG42 Piling Rig ruptured, oil ran down the hose line onto the ground in front of the rig, below the mast
Near miss	04/09/17	12:00	Rotary site	Spill	Hydraulic hose burst	A Commachio 205 rotary rig bar braided hydraulic hose blew causing hydraulic oil to spray approximately 0.5m into the air. The hydraulic oil spill was contained and mopped up immediately by the drillers using absorbent mats from their spill kit. Contaminated spoil was collected and placed in a sealed polythene bulk bag. A new hose was sourced and the hose repaired on site by Pirek. The site supervising engineers from Jacobs witnessed the incident.
Minor Incident	06/10/17	10:00am	CFAD/FA site	Spill	Faulty concrete pump	The pump operator was filling a pile when a hydraulic pipe burst leaking oil into the catchment tray provided below, due to the location of the pipe only a small amount of oil was found to be on the soil. A spill kit was immediately put to use with all contamination removed delivered back to the yard for disposal
Minor Incident	7.7.17	8:00	CFAD/FA site	Spill	maintenance to plant	Attending excavator burst a hose on site. Small incident which was cleaned up immediately
Minor Incident	05/07/17	12:30:00	Rotary site	Spill	Mechanical	Pile removal activities were carried out at the moment of the incident. 500mm reinforced piles were being removed. At the moment of the incident the auger caught an extremely hard part of the pile (concrete + reinforcement, 32B bars approx.). One of the hose couplers from the rotary head loosened and came free.
Minor Incident	10/07/17	22:50	CFAD/FA site	Spill	Mechanical	Upon auger extraction during the concreting phase of P8326, the drop hose got caught on the auger string causing it to create a slice through the hose and bursting.
Minor Incident	25/08/17	10:20	Rotary site	Spill	Mechanical	As the SR75 was spinning off, the gearbox on the rotary table failed causing the oil to leak from under the rotary table