

SERVICE STRIKES - Q1/2017

Approx. Date	Electricity	Gas	Water	Other (please specify)	Was a Permit to Work in place?	Details
08/03/2017				BT Cable	Yes	Pile was driven straight though BT Cable. Cable was not in location as shown on service location drawing.
31/03/2017		1			Yes	Digging a service pit prior to commencing drilling when they struck and damaged a domestic gas pipe that was 100mm bgl. Pipe was on drawings over 1metre away
11/01/2017		1			Yes	Permit to Dig (No. 5) for the working area was signed off yesterday (Tuesday 11:00 10/01/2017) confirming no services within 5m. During penetration of the vibrator, a gas main was struck at shallow depth.
07/02/2017			1		Yes	We had installed columns on plots 80 and 81 the previous day, however during a field inspection prior to work on the following morning the Supervisor noticed water sitting and bubbling through the platform in area of completed works.
01/03/2017			1		Yes	Whilst drilling within a pre marked and installed casing installed by the client the mini rig struck a water main on a waste water treatment site resulting in a significant water leak.
01/03/2017	1				Yes	During drilling on a pile position set out by the client, power was lost on the site however this was not reported to SW. During the removal of the auger it was observed there was an electrical cable wrapped around the auger and it was later confirmed to be the cause of the power loss.
30/03/2017			1		Yes	Whilst drilling a pile the auger exerted pressure on to water pipe and caused it to fracture
08/02/2017	1				Yes	Works proceeded under a permit, known cable had not been positively identified

Total: 2 2 3 1

Overall Number of Service Strikes: 8