

ref	Accident Severity / Category	Date of accident (dd/mm/yy)	Age	N° years experience	Shift start time (24 Hr)	Time of accident (24 Hr)	Place of Accident	Foundation Site Activity	Function / Trade (at time of accident)	Activity of IP (at time of accident)	Body part injured	Type of Injury	Basic cause	Outline / Description
2017/080	+7 day LTA	01/02/17	20	< 1 year	7.00	8.30	Site	CFA/DFA site	General Piling Operative	Mechanical handling	Finger / Thumb	Laceration	Trapped	The Injured Person was opening auger gates by pushing them open. The rig driver closed the ram on the locking mechanism whilst the IP's hand was still on the gate trapping the IP's left index finger and causing a laceration. Surgery was required to re attach the fingernail.
2017/081	1 -7 day LTA	20/01/17	39	>3 years	8.00	1415	Factory	Factory Premises	Workshop /Factory Operative	Mechanical handling	Finger / Thumb	Other	Contact with machinery	IP trapped finger between rebar and machine during fabrication process causing instant numbness to finger ends. <ul style="list-style-type: none"> • Retrofit guard fitted to danger area • Modifications made to prevent snagging of the rebar when dropped • Full SSoW produced based on the verbal training given by manufacturer on hand-over
2017/082	Specified Injury	29/03/17		>3 years	7.00	7.40	Factory	Factory Premises	Manager/Supervisor	Maintenance	Leg	Fracture	Contact with machinery	During maintenance the IP was inspecting automated rebar machine to ascertain location and cause of a possible fault. During this time the IP twisted and moved suddenly losing his footing causing his foot to become lodged within the footplate area and eventually falling to the ground landing on his left thigh. The Safety isolation had been over-ridden by the Maintenance Operative to check a fault and Op was stood in the danger zone when he tried to step out of the path of the return carriage he fell against the carriage which in turn re-activated the isolation but he fell onto his leg leg fracturing his femur in the process.
2017/083	1 -7 day LTA	06/03/17	45	>3 years	07:30:00	14:50:00	Site	CFA/DFA site	General Piling Operative	Other	Finger / Thumb	Fracture	Trapped	Whilst being employed as a slinger and during the landing "BOG MATS" the "IP" managed trap one of his fingers between the stationary mat and the mat that was being lowered resulting in a >7 day RIDDOR reportable injury.
2017/084	1 -7 day LTA	19/12/16	51	>3 years	07:30:00	10.25	Site	CFA/DFA site	Mixer / Pump man	Walking	Leg	Other	Contact with machinery	Whilst working within the vicinity of the concrete pump / mixer area the "IP's" knee collided with the vibrating concrete hose linking the mixer drum and the pump.
2017/085	Specified Injury	03/02/17	43	>3 years	08:00:00	11:00:00	Site	Rotary site	General Piling Operative	Maintenance	Finger / Thumb	Other	Trapped	Traffic marshal was conducting usual duties on site, when he was asked by the driver of a tipper wagon for Primagrang to check whether the tailgate was closed. The traffic marshal identified an obstruction within the locking mechanism and attempted to clear it with his finger. The driver of the vehicle operated the air switch at the same time as the traffic marshal attempted to clear the obstruction, which caught his finger within the locking mechanism causing partial amputation.
2017/086	Specified Injury	15/02/17	45	>3 years	08:00:00	09:30:00	Site	Rotary site	Other Sub Contractor	Walking	Finger / Thumb	Laceration	Trip / Slip	IP tripped on timber, put his hand out to steady himself and obtained a cut on little finger on left hand.
2017/087	Specified Injury	16/03/17	29	>3 years	08:00:00	14:05:00	Site	Rotary site	General Piling Operative	Walking	Chest	Other	Struck by	Piling rig attendant was struck in the abdomen by a combination of a flying projectile of clay and the pedestrian barrier he was stood behind. The clay was discharged when spinning off an auger, with the IP stood in front of the piling rig. IP underwent full body examination, IP diagnosed with 'mild right sided abdominal tenderness' and advised to return if conditions worsen or any further symptoms develop. IP returned to work capable of and resumed normal work duties – No lost time incurred
2017/088	+7 day LTA	06/02/17		< 1 year	7.30	9.45	Site	Rotary site	General Piling Operative	Walking	Shoulder	Other	Trip / Slip	The injured party was tidying to the D-wall area when the injury occurred. Whilst walking across site one of his feet slipped on loose gravel, causing him to stumble forward and hit the ground. This is likely to have caused him pain to his shoulder.
2017/089	1 -7 day LTA	24/02/17	33	>3 years	17:31:12	11am	Site	CFA/DFA site	General Piling Operative	Manual Handling - other manual handling	Arm	Other	Manual handling	Ip was carrying a piece of steel, he slipped on some clay,as he landed on the ground the piece steel landed on his shoulder.
2017/090	Specified Injury	26/01/17	53	>3 years	14.00	18.45	Yard	Factory Premises	Workshop /Factory Operative	Mechanical handling	Ankle / Foot	Fracture	Struck by	Whilst moving some 250mm diameter steel tubes at 7m length with a forklift, IP was struck on the foot when a tube moved inadvertently and hit his leg. No specific risk assessment or SSoW in place.
2017/091	+7 day LTA	17/02/17	46	1-3 years	7.30	13.30	Site	Driven site	General Piling Operative	Welding	Ankle / Foot	burn	Splashed	Whilst using oxy fuel equipment to cut a previously installed steel tube, IP sustained a burn to his foot when molten metal penetrated his boots. Spats provided worn but taken off as were catching when walking about all day - wear only when cutting.
2017/092	1 -7 day LTA	24/02/17	45	>3 years	6.00	9.00	yard	Factory Premises	Delivery/RMC Driver	Walking	Back	sprain/strain	Trip / Slip	IP was stepping out of his cab when he tripped over a speed bump in the immediate vicinity
2017/093	1 -7 day LTA	15/02/17	30	>3 years	7am	11am	Site	Rotary site	General Piling Operative	Manual Handling - Assembling	Finger / Thumb	Fracture	Struck against	The IP was removing a drill rod from a string using a hammer when he missed fracturing a finger
2017/094	+7 day LTA	19/01/17	18	< 1 year	7.00 a.m.	10.45 a.m.	Site	Drilling/Minipile site	General Piling Operative	Mobilisation / demobilisation	Back	Other	Trapped	IP caught between forklift outrigger and delivery vehicle whilst banking.
2017/095	+7 day LTA	23/02/17	37	>3 years	7.00 a.m.	12.15 p.m.	Site	Drilling/Minipile site	General Piling Operative	Manual Handling - Assembling	Leg	Other	Trip / Slip	The IP was walking along boards carrying a 0.5m Kelly bar in his arms, His weight caused the board to sink into the gravels, this caused the IP to overbalance, his foot slipped into the spoil. His right leg sunk up to the top of his wellington boot the IP fell backwards with his foot still trapped in the gravel.