

Sirius Minerals Incident Flash



INCIDENT TYPE	OMEGA REFERENCE	DATE OF INCIDENT	INCIDENT TITLE
Crush Injury	REP-18-000583	16 th July 2018	Plant/person contact
DESCRIPTION OF INCIDENT			
<p>Zublin (Strabag Piling Contractor) were carrying out piling activities in Zone A of the Wilton Site. Whilst the Rig Operator was slewing the Piling Rig, the Rig Handler (Banksman) was caught between the rig and the casing resulting in the IP sustaining injuries that required Air Ambulance support and transfer to A&E.</p>		<p>POST INCIDENT MANAGEMENT</p> <ul style="list-style-type: none"> All Works on site stopped until further notice All relevant parties informed of incident Mines inspectorate (HSE) informed Investigation begun including taking witness statements and breathalysing those involved 	
			<p>Person caught between the rear of the rig and casing as displayed above</p>
AREAS OF FOCUS / NEXT STEPS			
<p>Wilton Site, Zone A, showing the Piling Rig and where the IP was located prior to the incident</p> <ul style="list-style-type: none"> Thorough Investigation to be carried out by the Principal Contractor with involvement from Sirius Minerals and specific external personnel. No further work to begin until Review of all activities with Zone A work area has been carried out. Briefing to all Site Personnel prior to work recommencing with the focus on Plant and Personnel interaction 	<p>Piling Rig & Piling Steel Casing</p>	<p>AREAS FOR REVIEW</p> <ul style="list-style-type: none"> A review of the Piling Safe System of Work to be carried out Functionality and Engineering Controls of Piling Rig Training & Competency Review of site safety behaviour 	