

---

# Health & Safety Incident Report

## >3 Day Ankle Injury, Battersea, BBGE

---

- **What happened?**

- The injured person was walking along side the lorry while looking up toward the load. His foot stepped into a depression in the ground and he turned his ankle resulting in ligament damage.

14<sup>th</sup> July 2017

- **What were the details?**

- The platform had been previously inspected and no concerns were raised.
- The depression may have been caused by drainage along a concrete barrier that had been there previously

- **What can we learn?**

- The platform should be levelled off regularly with ruts and depressions backfilled. Platform condition must be suitable for pedestrians to use, not just plant and vehicles

